

V.M.S
4990

Bullard Survey Cooper Ave. Part of Lot @ 1061 August 1965

The following described being the east end of Lot Number 1061 and being in Bellefontaine, Lake Township, Logan County, Ohio

Beginning at an iron in the center of the Ludlow Road and the center of Cooper Ave. Thence with the center of Cooper Ave. S $72^{\circ} - 00'$ E. 111.75 feet to a small iron.

Thence N. $15^{\circ} - 15'$ E. 15.00 feet to an iron at the north side of Cooper Ave. Said iron being the beginning point of this survey.

Thence again N. $15^{\circ} - 15'$ E. 58.00 feet to a round wood post.

Thence with the north side of Lot Number 1061 and with the south side of Lot Number 1060 S. $76^{\circ} - 50'$ E. 41.70 feet to a round wood post at the N.E. corner of Lot Number 1061.

Thence with the east side of Lot Number 1061 S. $3^{\circ} - 55'$ W. 63.40 feet to an iron at the north side of Cooper Ave.

Thence with the north side of Cooper Ave. N. $72^{\circ} - 00'$ W. 54.35 feet to the place of beginning.

cc
Logan County Engineer



INDEXED ON MAP

3844

ID

On plat book
11/20/65
D.E.G.