



3-16-43 Iron bar found and recognized as corner  
reestablished from old surveys.  
The above mentioned iron was removed and concrete  
monument set at this point 3 inches below  
road surface

Hane Kerns  
Fay Hurst  
R. H. Reed

MONUMENT stamped as directed above

3/20/43

R.H.R.

