



No 4  
U.M. Stites

No 5  
Sarah A. Cost  
16.25 a

24 a

No 2  
S 87° 50' E, 400' 438

S 87° 26' E 164' 204'

No 1  
S 87° E 157'

Daniel Clark  
1 a

Sarah Cost  
2 a

Quincy Pike  
b. b. b.

St. L. R.W.

No 7  
J.S. Knoop  
6 a

No 6

very flat  
drainage main in  
under

John C. Smith  
19.39 a

slopes west

No. 3  
Wm. J. Curl  
21.45 a

Map & Plat of the  
Sarah A. Cost Ditch

In Quincy Precinct, Miami Township

J.C. Wanders, Co. Sur. H.C. Moore Supt.  
of Engineers

Aug 3 1892